Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: KOALA 3-2-11-14H

Field Name: POE Well File #: 19961

Date Incident: 9/25/2016 Time Incident: 19:30 Facility ID Number:

County: MCKENZIE Twp: 151 Rng: 100 Sec: 2 Qtr: NW NE

Location Description:

Submitted By: Patrick McNamara Received By:

Contact Person: Patrick McNamara

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:0.8 MileDistance Nearest Water Well:0.8 Mile

Type of Incident: Treater Popoff

Release Contained in Dike: No Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits7Barrels7Barrels7barrels

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 11/14/2016 Clean Up Concluded: 10/11/2016

Risk Evaluation:

None noted.

Areal Extent:

Roughly 100 yards by 50 yards of pasture to the southwest of the constructed well pad.

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

The flare was shut in to stop the flow of oil. Fluid on the constructed well location will be sucked up and the impacted facility soil will be scraped up from the location. The grass in the pasture will be mowed and picked up. Monitor and inspect treaters on a routine basis.

Wastes Disposal Location: Republic Services Disposal.

Agencies Involved:

Updates

Date: 9/26/2016 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Date: 9/27/2016 Status: Inspection Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 9/27/2016, at 12:06 p.m. Spray from flare went off location to the southeast. Area is approximately 60 X 50 yards of pasture land. Oil is visible on fence surrounding the pad and vegetation in area. More follow-up is required once cleanup is completed.